# Part Number: PT226-34220

## Kit Contents

| Item # | Quantity Reqd. | Description |
|---|---|---|
| 1 | 1 | Tail Pipe, P/N PT226-34220-00 |
| 2 | 2 | Nut, Lock, P/N 90177-A0021 |
| 3 | 1 | Gasket, P/N 17451-F4010 |
| | | |

## Vehicle Service Parts (may be required for reassembly)

| Item # | Quantity Reqd. | Description |
|---|---|---|
| 1 | 1 | Gasket, P/N 17451-F4010 |
| 2 | 2 | Nut, Lock, P/N 90177-A0021 |
| | | |
| | | |

## Hardware Bag Contents

| Item # | Quantity Reqd. | Description |
|---|---|---|
| 1 | 2 | Nut, Lock, P/N 90177-A0021 |
| 2 | 1 | Gasket, P/N 17451-F4010 |
| 3 | | |
| | | |

## Legend

**STOP:** Damage to the vehicle may occur. Do not proceed until process has been complied with.

**OPERATOR SAFETY:** Use caution to avoid risk of injury.

**CAUTION:** A process that must be carefully observed in order to reduce the risk of damage to the accessory/vehicle and to ensure a quality installation.

**TOOLS & EQUIPMENT:** Used in Figures calls out the specific tools and equipment recommended for this process.

**REVISION MARK:** This mark highlights a change in installation with respect to previous issue.

**SAFETY TORQUE:** This mark indicates that torque is related to safety.

**REGULATORY MARK:** This mark indicates the component is related to regulatory compliance

## Additional Items Required For Installation

| Item # | Quantity Reqd. | Description |
|---|---|---|
| 1 | | |
| 2 | | |
| 3 | | |
| | | |

## Conflicts

None

## Recommended Tools

| Personal & Vehicle Protection | Notes |
|---|---|
| | |
| | |
| | |
| **Special Tools** | **Notes** |
| | |
| | |
| | |
| **Installation Tools** | **Notes** |
| 14mm Socket | |
| Exhaust Hanger Tool | |
| Torque Wrench | |
| **Special Chemicals** | **Notes** |
| | |
| | |
| | |

## General Applicability

MY22 and newer Tundra models Applies to TRD PRO vehicles only.

## Recommended Sequence of Application

| Item # | Accessory |
|---|---|
| 1 | Remove Spare Tire |
| 2 | Remove OE Tail Pipe |
| 3 | Install TRD Tail Pipe |
| 4 | Replace Spare Tire |

*Mandatory



**Issue: A 02/22/2022**

Care must be taken when installing this accessory to ensure damage does not occur to the vehicle. The installation of this accessory should follow approved guidelines to ensure a quality installation.

These guidelines can be found in the "Accessory Installation Practices" document.

This document covers such items as:-

- Vehicle Protection (use of covers and blankets, cleaning chemicals, etc.).
- Safety (eye protection, rechecking torque procedure, etc.).
- Vehicle Disassembly/Reassembly (panel removal, part storage, etc.).
- Electrical Component Disassembly/Reassembly (battery disconnection, connector removal, etc.).

Please see your Toyota dealer for a copy of this document.

## 1. Preparation & Warnings.

(a) Vehicle Protection Warning (if applicable.)

(b) To prevent burns, do not touch the engine, exhaust pipe or other high temperature components while the engine is hot.

## 2. Remove Spare Tire & OE Tail Pipe.

(a) Lower spare tire.

(b) Remove OE Tail Pipe (Fig. 2-1).




Fig. 2-1

## 3. Install TRD Tail Pipe & Replace Spare Tire.

(a) Place Tail Pipe.

(b) Attach hangers (2 places).

(c) Hand start lock-nuts on studs.

(d) Snug fasteners and remove bubble wrap.

(e) Confirm tip x bumper spacing, 30 ± 5mm. Adjust if necessary.

**Torque Bolts to 43.0 N-m (31.7 lb-ft).**

(a) Secure spare tire.



**Issue: A 02/22/2022**

Checklist - these points **MUST** be checked to ensure a quality installation.

| Check: | Look For: |
|---|---|
| Accessory Function Checks | |
| ☐ Confirm torque. | 43.0 N-m (31.7 lb-ft) |
| ☐ Confirm exhaust tip x bumper spacing. | 30 ± 5mm |
| ☐ | |
| ☐ | |
| Vehicle Function Checks | |
| ☐ Confirm no exhaust leaks. | |
| ☐ | |
| ☐ | |
| Vehicle Appearance Check | |
| ☐ After accessory installation and removal of protective cover(s), perform a visual inspection. | Ensure no damage (including scuffs and scratches) was caused during the installation process. (For PPO installations, refer to TMNA Accessory Quality Shipping Standard.) |



**Issue: A 02/22/2022**