TOYOTA TACOMA/HV, 4RUNNER HV 2024 -, RAV4 HV 2026- IP Side Lantern

Preparation

Part Number: PT944-35253

Kit Contents

Item #	Quantity Reqd.	Description
1	1	Organizer
1	1	Lantern

Hardware Bag Contents

Item #	Quantity Reqd.	Description
1		
2		
3		
4		
5		

Additional Items Required For Installation

Item #	Quantity Reqd.	Description
1		
2		
3		

Conflicts

None

Recommended Tools

Personal & Vehicle Protection	**No need any protection**
Special Tools	**No tool needed.**

General Applicability

MY24 and newer Tacoma/HV, 4Runner models

Recommended Sequence of Application

Item #	Accessory
1	
2	

*Mandatory

Vehicle Service Parts (may be required for reassembly)

Item #	Quantity Reqd.	Description
1		
2		
3		

Legend

STOP: Damage to the vehicle may occur. Do not proceed until process has been complied with.

OPERATOR SAFETY: Use caution to avoid risk of injury.

CAUTION: A process that must be carefully observed in order to reduce the risk of damage to the accessory/vehicle and to ensure a quality installation.

TOOLS & EQUIPMENT: Used in Figures calls out the specific tools and equipment recommended for this process.

REVISION MARK: This mark highlights a change in installation with respect to previous issue.

SAFETY TORQUE: This mark indicates that torque is related to safety.

Issue: D 12/16/2025

© 2025 Toyota Motor Sales, USA



Fig. 1-1

1. Preparation before fit.

(a) Twist the Lantern to remove it from the Organizer (Fig.1-1).




Fig. 2-1

2. Remove the Cover at Driver side Instrument panel and Install the Organizer

(a) Remove the Cover at driver side Instrument panel by pulling the Cover / disengaging the hooks located at the Cover and (Fig. 2-1).

(b) Place cover in glove box




Fig. 2-2

(c) Install the Organizer to the vehicle. With the ⇧ mark on the back facing upward, fix the four hooks (Fig.2-2)

Issue: D 12/16/2025

© 2025 Toyota Motor Sales, USA




Fig. 2-3

(d) Check that the four hooks are fit (Fig.2-3).

3. Mounting the Lantern.

(d) Locate Lantern and twist to lock into the position (Fig.3-1).



Fig. 3-1

Issue: D 12/16/2025

© 2025 Toyota Motor Sales, USA

Accessory Function Checks

- [ ] Ensure that the part is secure to the IP
- [ ] Ensure that the Toyota Logo is upright
- [ ] Ensure removed panel is placed in glove box

Vehicle Function Check

Vehicle Appearance Check

Issue: D 12/16/2025

© 2025 Toyota Motor Sales, USA